						Overall	% Life			CONSE	QUENCE	S OF FA	III URF						
						Condition	Left as		(				ROGRAN	1)		Threshold	Threshold		
	EV201E	2010 CID b D	ul a ultur					DAT						•		Tillesilolu	Tillesiloid		
	F12015-	2019 CIP by P	riority			input 2	input 1	9.0	INGS AN	8.0	10.0	No impac 5.0	7.0	High im 6.0	6.0			_	
01.1						Overall	% Life Left	3.0	0.0			3.0	7.0	0.0					
Old Priorit Y	Priority	Project Title	Project Description / Justification	Comments	Est Cost in FY2014	Condition 0: Worse to 10: Best	0: Expired to 100: New	City Operations	Programs / Services	Costs/ Savings Ratio	Codes/ Health & Safety	Property Damage	Quality of Life	Energy	Dept. Mission or Vision	Likelihood of Failure	Conseq. Factor	Risk Factor	Funding Source
67		City Hall - Plumbing and Accessiblity Improveme nts	Upgrade toilet rooms for improved accessibility as required by code.	Repair, upgrade finishes, in all bathrooms(10ea =2500sf)	\$ 105,00	2	10%	6	8	4	7	0	8	1	8	0.833	5.51	45.9	Bonding
75	34	City Hall - Envelope -	On-going program to repair and repoint exterior masonry to preserve building envelope. Address worst areas first.		\$ 253,00	0 3	30%	8	6	6	6	8	6	2	8	0.700	6.28	44.0	Bonding
133		Upgrades	Replace and insulate ductwork and replace fans. Add mini-split A/C	Standard condensing unit which is very corroded. Provide cover for units in winter. *Replace Dayton condensing unit which is very corroded. Provide cover for units in winter. *Provide insulation for all supply ductwork and clean all ductwork.	\$ 425,00	0 3	10%	7	6	6	5	4	6	4	7	0.767	5.70	43.7	Bonding
				Replace two floor mounted centifugal fans in attic for bathrooms (2400CFM) Replace two horizontal fan coil units in the attic. Replace floor mounted centrifugal fan in attic for central exhaust (1ea). Replace floor mounted centrifugal fan in attic for Memorial Hall (1ea). Replace floor mounted centrifugal fan in ctupola for cafteria (2ea)  Replace all ceiling fans with energy efficient fans. Replace damaged grilles (20%). Replace all bathroom fans with new															
				energy efficient fans. Add mini-split A/C units in conjunction with window restoration /replacement (\$100K). Maintenance items removed from list.															

						Overall	% Life			CONSE	QUENCE	S OF FA	AILURE						
						Condition	Left as		(	IF NOT I	MPLEME	NTING P	ROGRAM	1)		Threshold	Threshold		
	FY2015-	2019 CIP by P	riority			input	input	RAT	,		HTS0 (I			•	pact)				
						2	1	9.0	6.0	8.0	10.0	5.0	7.0	6.0	6.0			-	
Old Priorit Y	Priority	Project Title	Project Description / Justification	Comments	Est Cost in FY2014	Overall Condition 0: Worse to 10: Best	% Life Left 0: Expired to 100: New	City Operations	Programs / Services	Costs/ Savings Ratio	Codes/ Health & Safety	Property Damage	Quality of Life	Energy	Dept. Mission or Vision	Likelihood of Failure	Conseq. Factor	Risk Factor	Funding Source
	87	City Hall - Roof Repair/ Replacemen t	Install new membrane roof on flat roofs. Repair/replace gutters on balcony roofs. Replace metal roofing/flashing as req'd.	Install new EPDM membrane roof (6000sf) on main flat roofs. Replace membrane roofing on inside upper floor of large cupola. Replace exit door from cupola to exterior walk- around and add closer and locking mechanisms. Repair roof flashing and repair/replace gutters (700sf) on balcony roofs. *Replace metal roofing and flashing as required at several small sloping metal roofs (200sf).	\$ 226,218		10%	8	6	3	3	8	6	2	8	0.700	5.33	37.3	Bonding
29	106	City Hall - Sprinklers and Fire Alarm Upgrades	Plan installation of sprinkler system and addressable fire alarm upgrades in City Hall in conjunction with other building upgrades.		\$ 1,215,000	4	40%	8	7	5	8	7	4	0	8	0.600	6.05	36.3	Bonding
176	107	City Hall - Electrical Upgrades	Replace emergency generator and electrical upgrades.		\$ 225,000	3	10%	8	6	2	5	2	2	4	8	0.767	4.74	36.3	Bonding
198	148	City Hall - Repair Front stone entry stairs and Accessible Ramp	Rebuild accessible ramp. Repair and repoint stone cornice. Rebuild/reset main entry stairs and install code-compliant railings.	Rebuild access ramp located at middle right side of building (70sf). Repair and repoint deteriorated areas of stone cornice (20%= 300ff). Repair minor damaged areas of metal skin siding at large cupola (200sf). Rebuild/reset front main	\$ 324,000	3	30%	6	6	4	8	6	4	0	4	0.700	4.98	34.9	Bonding
				reduito/reset front main entry stone stairs and stone wing walls and install code-compliant railings (10r triple-wide). Replace or repair damaged stone treads. Rebuild/reset both front side entry stone stairs and install code-compliant railings (5r double-wide). Repair, reset and repoint stair treads and handrails at four locations (6R at each location).															

						Overall	% Life			CONSE	QUENCE	S OF FA	AILURE						
						Condition	Left as		(				ROGRAM	)		Threshold	Threshold		
	FY2015-	2019 CIP by P	riority			input	input	RAT					et) to 10 (		pact)				
						2	1	9.0	6.0	8.0	10.0	5.0	7.0	6.0	6.0			-	
Old Priorit Y	Priority	Project Title	Project Description / Justification	Comments	Est Cost in FY2014	Overall Condition 0: Worse to 10: Best	% Life Left 0: Expired to 100: New	City Operations	Programs / Services	Costs/ Savings Ratio	Codes/ Health & Safety	Property Damage	Quality of Life	Energy	Dept. Mission or Vision	Likelihood of Failure	Conseq. Factor	Risk Factor	Funding Source
				Rebuild/reset rear stone stairs and install code-compliant railings (20r). Rebuild and repoint stone corner posts at rear stairs (2 ea). Replace egress stairs from basement to exterior. Construct first three risers at basement level out of concrete to reduce future corrosion of steel (20r).															
268	189	City Hall - Plumbing Upgrades	Renovate toilet rooms and replace cold and hot water piping as required. Provide insulation for all piping.		\$ 137,000	4	20%	8	7	4	5	1	5	1	7	0.667	4.98	33.2	Bonding
286	218	City Hall - Kitchen Mechanical Upgrades	Repair, upgrade kitchen equipment and stove ventilation in cafeteria kitchen to comply with current code requirements.		\$ 168,000	3	30%	6	6	1	4	4	6	2	6	0.700	4.35	30.5	Bonding
47	42	City Hall - Exterior Windows & Doors	Restore/Replace windows in phases to improve energy efficiency, functionality and comfort, and to preserve exterior wall.	Restore/Replace windows. Repair, scrape, prepare surface and paint all exterior wood windows including double hung windows (143 ea), arched wood windows (36ea) and roof eyebrow wood windows (4ea). Repair rotted sills and jambs (4ea) and replace broken screens.	\$ 1,000,000	3	10%	6	5	4	4	8	5	6	8	0.767	5.53	42.4	CPA Eligible
305	121	City Hall - Rehabilitate Board of Alderman Chamber	Upgrade Historic Board Chamber to improve mechanical, electrical, audio/visual systems and lighting and interior finishes.	There has been continuing deterioration of the space as it passes its 75th anniversary. Desks and chairs need restoration. Aldermen are unable to effectively use electronic devices due to limited number of power outlest. Lighting is inadequate for NewTV to effectively capture images for broadcast. The sound system is also inadequate and may need to be rewired. There continues to be the need to provide appropriate access to Legislative meetings.	\$ 250,000	2	20%	8	6	0	4	1	6	0	10	0.800	4.47	35.8	CPA Eligible

						Overall	% Life				QUENCE								
	E)/204E	2040 010 1 0				Condition	Left as						ROGRAM	•		Threshold	Threshold		
	FY2015-	2019 CIP by P	riority			input 2	input 1	9.0	NGS AN	8.0	1150 (I   10.0	<u>vo impac</u>   5.0	ct) to 10 (	Hign im 6.0	6.0			_	
Old Priorit y	Priority	Project Title	Project Description / Justification	Comments	Est Cost in FY2014	Overall Condition 0: Worse to 10: Best	% Life Left 0: Expired	City Operations	Programs / Services	Costs/ Savings Ratio	Codes/ Health & Safety	Property Damage	Quality of Life	Energy	Dept. Mission or Vision	Likelihood of Failure	Conseq. Factor	Risk Factor	Funding Source
				Restore, Repair and Refinish wood floors and historic woodwork in chamber. Repair water damage to ceiling, and walls and paint walls and ceiling, improve lighting, improve sound system, impprove accessibility, and install additional electrical capacity to allow use of electronic devices and add air conditioning.															
86		City Hall - Masonry Restoration of War Memorial Steps	Implement recommendations from 2007 Study of the Memorial Stairs.		\$ 185,000	2	10%	6	6	0	6	6	4	0	6	0.833	4.28	35.7	CPA Eligible
253		City Hall - Increase City Clerk Archive Storage	Develop plans to expand archival storage to accommodate and preserve archival collections and to comply with MGL mandated record storage requiremts.	The only city Archival Storage space is in the Newton Free Library and is 95% full. Needs to be expanded to accommodate MGL mandated record storage and preservation into the future. A plan needs to be developed to address this critical need before space runs out.	\$ 100,000	3	30%	7	8	4	0	6	6	0	10	0.700	4.82	33.8	CPA Eligible
		City Hall - War Memorial Auditorium HVAC	Restore historic hall to improve mechanical & electrical systems.		\$ 150,000	3	10%	6	8	0	2	0	7	0	10	0.767	4.05	31.1	CPA Eligible
284		City Hall and War Memorial Historic Landscape Preservatio n Project	Restoration and preservation of City Hall grounds Historic Landscape	The most identifiable landscape in the City, City Hall/War Memorial Public Bldg, Grounds designed by Olmsted Bros. is on the National Historic Register. This landscape has deteriorated significantly since it was first built and requires significant work to restore.	\$ 1,500,000 6 263 218	3	50%	2	5	1	4	1	8	0	9	0.633	3.70	23.4	CPA Eligible

TOTAL COST \$ 6,263,218

Total listed as \$ 3,185,000

"CPA-eligible"

NOTE: A new elevator for the War Memorial wing of City Hall is not mentioned in any project listed in this edition of the CIP.